# Reporting – Remove Striping from First Article

*The default **First Article** report that comes with QC-CALC has white and gray backgrounds in every other row of the table. This White Paper will give step by step instructions for removing that striping.*

The Report Designer

The directions shown here will walk you through removing the striping in the table of the First Article report.

1. From QC-CALC Real-Time choose the **Report > Design Template** menu.

2. To view the Report Designer, choose the OnePiece.FST template from the list of files that appears and click **Open**.

Reporting – Remove Striping from First Article

## Using Objects Tab to Choose Table

3. In the middle of the left side of the screen, click the **Objects** tab to display a list of all objects in the report.

4. Find the "Table 1" item in the **Objects** area and click it. You will see a frame appear around the table in the middle of the screen as shown above.
5. Now that the table is selected, the **Properties** area in the lower left corner shows general table settings. Scroll down in the Properties area until the **Zebra Pattern** option is shown in the **Data Lines** area.

6. Choose the **Transparent** option from the list that appears when you click the down arrow.

Final Steps

7. Save your changes (**File > Save**), exit from the Report Designer, and run your report.
8. You should see the table without the white and gray lines in your report now.